








wire to wire connections






A	B	MOLD	P	W/M
10mm ²	10mm ²	WE-10/10	3	32
16	16	WE-16/16	3	32
25	25	WE-25/25	3	32
30	30	WE-30/30	3	32
35	35	WE-35/35	3	32
50	50	WE-50/50	3	45
70	70	WE-70/70	3	65
95	95	WE-95/95	3	90
120	120	WE-120/120	3	115
150	150	WE-150/150	3	115
185	185	WE-185/185	3	150
240	240	WE-240/240	3	200
300	300	WE-300/300	3	250
400	400	WE-400/400	3	2x150
500	500	WE-500/500	4	2x200
600	600	WE-600/600	4	2x200
725	725	WE-725/725	4	2x250
850	850	WE-850/850	4	3x250
1000	1000	WE-1000/1000	4	4x250
4/0 awg	4/0 awg	WE-100A/100A	3	115




A	B	MOLD	P	W/M
10mm ²	10mm ²	WT-10/10	3	32
16	16	WT-16/16	3	32
25	25	WT-25/25	3	45
25	16	WT-25/16	3	45
30	30	WT-30/30	3	45
	25	WT-30/25	3	45
	16	WT-30/16	3	45
35	35	WT-35/35	3	45
	30	WT-35/30	3	45
	25	WT-35/25	3	45
	16	WT-35/16	3	45
50	50	WT-50/50	3	65
	35	WT-50/35	3	45
	30	WT-50/30	3	45
	25	WT-50/25	3	45
	16	WT-50/16	3	45
70	70	WT-70/70	3	90
	50	WT-70/50	3	90
	35	WT-70/35	3	65
	30	WT-70/30	3	65
	25	WT-70/25	3	65
	16	WT-70/16	3	65
95	95	WT-95/95	3	115
	70	WT-95/70	3	90
	50	WT-95/50	3	90
	35	WT-95/35	3	90
	30	WT-95/30	3	90
	25	WT-95/25	3	65
	16	WT-95/16	3	65
120	120	WT-120/120	3	150
	95	WT-120/95	3	150
	70	WT-120/70	3	90
	50	WT-120/50	3	90
	35	WT-120/35	3	90
	30	WT-120/30	3	90
	25	WT-120/25	3	90
	16	WT-120/16	3	90




註解:


A	B	MOLD	P	W/M
150mm ²	150mm ²	WT-150/150	3	200
	120	WT-150/120	3	150
	95	WT-150/95	3	150
	70	WT-150/70	3	90
	50	WT-150/50	3	90
	35	WT-150/35	3	90
	30	WT-150/30	3	90
	25	WT-150/25	3	90
185	185	WT-185/185	3	200
	150	WT-185/150	3	200
	120	WT-185/120	3	200
	95	WT-185/95	3	150
240	240	WT-240/240	3	2x150
	185	WT-240/185	3	200
	150	WT-240/150	3	200
	120	WT-240/120	3	200
	95	WT-240/95	3	200
300	300	WT-300/300	4	2x200
	240	WT-300/240	4	2x200
	185	WT-300/185	3	250
	150	WT-300/150	3	200



A	B	MOLD	P	W/M
10mm ²	10mm ²	WX-10/10	3	32
16	16	WX-16/16	3	45
25	25	WX-25/25	3	45
30	30	WX-30/30	3	45
35	35	WX-35/35	3	65
35	25	WX-35/25	3	65
50	50	WX-50/50	3	90
50	35	WX-50/35	3	90
50	25	WX-50/25	3	90
70	70	WX-70/70	3	115
	50	WX-70/50	3	115
	35	WX-70/35	3	115
	25	WX-70/25	3	115
95	95	WX-95/95	3	150
	70	WX-95/70	3	150
	50	WX-95/50	3	115
	35	WX-95/35	3	115
120	120	WX-120/120	3	200
	95	WX-120/95	3	200
	70	WX-120/70	3	150
	50	WX-120/50	3	150
	35	WX-120/35	3	150
	25	WX-120/25	3	150
150	150	WX-150/150	3	250
	120	WX-150/120	3	250
	95	WX-150/95	3	200
	70	WX-150/70	3	150
	50	WX-150/50	3	150
185	185	WX-185/185	3	2x150
	150	WX-185/150	3	250
	120	WX-185/120	3	250
	95	WX-185/95	3	200
	70	WX-185/70	3	200
240	240	WX-240/240	4	2x250
	185	WX-240/185	4	2x200
	150	WX-240/150	4	2x200
	120	WX-240/120	4	2x150
	95	WX-240/95	4	250




A	B	MOLD	P	W/M
50mm ²	50mm ²	WXL-50/50	10	115
70	70	WXL-70/70	10	150
	50	WXL-70/50	10	150
	35	WXL-70/35	10	115
	25	WXL-70/25	10	115
95	95	WXL-95/95	10	200
	70	WXL-95/70	10	200
	50	WXL-95/50	10	150
	35	WXL-95/35	10	150
120	120	WXL-120/120	10	250
	95	WXL-120/95	10	250
	70	WXL-120/70	10	200
	50	WXL-120/50	10	200
	35	WXL-120/35	10	150
	25	WXL-120/25	10	150
150	150	WXL-150/150	11	2x200
	120	WXL-150/120	11	2x200
	95	WXL-150/95	10	2x150
	70	WXL-150/70	10	2x150
	50	WXL-150/50	10	200
185	185	WXL-185/185	11	3x200
	150	WXL-185/150	11	2x250
	120	WXL-185/120	11	2x250
	95	WXL-185/95	11	2x200
	70	WXL-185/70	10	2x150
240	240	WXL-240/240	11	3x250
	185	WXL-240/185	11	3x200
	150	WXL-240/150	11	3x200
	120	WXL-240/120	11	2x250
	95	WXL-240/95	11	2x250



WP


Note: two wires parallel into top-down

A	B	MOLD	P	W/M
10mm ²	10mm ²	WP-10/10	3	45
16	16	WP-16/16	3	45
25	25	WP-25/25	3	45
30	30	WP-30/30	3	65
35	35	WP-35/35	3	65
35	30	WP-35/30	3	65
50	50	WP-50/50	3	90
50	35	WP-50/35	3	90
50	25	WP-50/25	3	65
70	70	WP-70/70	3	115
	50	WP-70/50	3	115
	35	WP-70/35	3	90
	30	WP-70/30	3	90
95	95	WP-95/95	3	150
	70	WP-95/70	3	150
	50	WP-95/50	3	115
	35	WP-95/35	3	115
120	120	WP-120/120	3	200
	95	WP-120/95	3	200
	70	WP-120/70	3	150
	50	WP-120/50	3	150
150	150	WP-150/150	4	2x150
	120	WP-150/120	3	250
	95	WP-150/95	3	200
	70	WP-150/70	3	150
185	185	WP-185/185	4	2x150
	150	WP-185/150	4	2x150
	120	WP-185/120	3	250
	95	WP-185/95	3	200
240	240	WP-240/240	4	2x200
	185	WP-240/185	4	2x150
	150	WP-240/150	4	2x150
	120	WP-240/120	4	250
300	300	WP-300/300	4	500
	240	WP-300/240	4	500
	185	WP-300/185	4	2x200
300 4/0 AWG	150	WP-300/150	4	2x150
	95	WP-100A/95	3	150



Note: two wires parallel into horizon

A	B	MOLD	P	W/M
10mm ²	10mm ²	WF-10/10	3	45
16	16	WF-16/16	3	65
25	25	WF-25/25	3	45
30	30	WF-30/30	3	45
35	35	WF-35/35	3	65
35	25	WF-35/25	3	65
50	50	WF-50/50	3	90
	35	WF-50/35	3	90
	25	WF-50/25	3	90
70	70	WF-70/70	3	115
	50	WF-70/50	3	115
	35	WF-70/35	3	90
	25	WF-70/25	3	90
95	95	WF-95/95	3	150
	70	WF-95/70	3	150
	50	WF-95/50	3	150
	35	WF-95/35	3	115
120	120	WF-120/120	3	200
	95	WF-120/95	3	200
	70	WF-120/70	3	200
	50	WF-120/50	3	150



A	B	MOLD	P	W/M
10mm ²	10mm ²	WL-10/10	3	45
16	16	WL-16/16	3	45
25	25	WL-25/25	3	45
30	30	WL-30/30	3	45
35	35	WL-35/35	3	45
35	25	WL-35/25	3	45
50	50	WL-50/50	3	90
	35	WL-50/35	3	65
	25	WL-50/25	3	65
70	70	WL-70/70	3	115
	50	WL-70/50	3	115
	35	WL-70/35	3	90
	25	WL-70/25	3	90
95	95	WL-95/95	3	150
	70	WL-95/70	3	115
	50	WL-95/50	3	115
	35	WL-95/35	3	115
120	120	WL-120/120	3	200
	95	WL-120/95	3	200
	70	WL-120/70	3	150
	50	WL-120/50	3	115