









*busbar/strap to busbar connections*






A	MOLD	P	W/M
2x20 <sub>mm</sub> <sup>2</sup>	BE-0220	3	45
3x20	BE-0320	3	45
2x25	BE-0225	3	65
3x25	BE-0325	3	65
4x25	BE-0425	3	90
2x30	BE-0230	3	65
3x30	BE-0330	3	90
4x30	BE-0430	3	115
5x30	BE-0530	3	115
3x40	BE-0340	3	115
4x40	BE-0440	3	150
5x40	BE-0540	3	150
6x40	BE-0640	3	200
5x50	BE-0550	3	200
6x50	BE-0650	3	250
8x50	BE-0850	4	2x150
6x60	BE-0660	3	250
8x60	BE-0860	4	2x200
10x60	BE-1060	4	500
6x80	BE-0680	4	2x200
8x80	BE-0880	4	500
10x80	BE-1080	4	3x200


BEH



A	MOLD	P	W/M
2x20mm <sup>2</sup>	BEH-0220	3	45
3x20	BEH-0320	3	45
4x20	BEH-0420	3	65
5x20	BEH-0520	3	90
2x25	BEH-0225	3	45
3x25	BEH-0325	3	65
4x25	BEH-0425	3	90
5x25	BEH-0525	3	90
2x30	BEH-0230	3	65
3x30	BEH-0330	3	65
4x30	BEH-0430	3	90
5x30	BEH-0530	3	115
3x40	BEH-0340	3	65
4x40	BEH-0440	3	65
5x40	BEH-0540	3	90
6x40	BEH-0640	3	115
5x50	BEH-0550	4	200
6x50	BEH-0650	4	250
8x50	BEH-0850	4	2x150
6x60	BEH-0660	4	2x150
8x60	BEH-0860	4	2x200
10x60	BEH-1060	4	500




A	MOLD	P	W/M
2x20 <sub>mm</sub> <sup>2</sup>	BTV-0220	3	45
3x20	BTV-0320	3	65
2x25	BTV-0225	3	65
3x25	BTV-0325	3	65
4x25	BTV-0425	3	90
2x30	BTV-0230	3	65
3x30	BTV-0330	3	90
4x30	BTV-0430	3	115
5x30	BTV-0530	3	115
3x40	BTV-0340	3	115
4x40	BTV-0440	3	150
5x40	BTV-0540	3	150
6x40	BTV-0640	3	200
5x50	BTV-0550	3	200
6x50	BTV-0650	3	250
8x50	BTV-0850	3	2x150
6x60	BTV-0660	4	2x150
8x60	BTV-0860	4	2x200
10x60	BTV-1060	4	500
6x80	BTV-0680	4	2X200
8x80	BTV-0880	4	500
10x80	BTV-1080	4	3X200




A	MOLD	P	W/M
2x20 <sub>mm</sub> <sup>2</sup>	BT-0220	3	45
3x20	BT-0320	3	45
4x20	BT-0420	3	65
5x20	BT-0520	3	90
2x25	BT-0225	3	45
3x25	BT-0325	3	65
4x25	BT-0425	3	90
5x25	BT-0525	3	90
2x30	BT-0230	3	65
3x30	BT-0330	3	65
4x30	BT-0430	3	90
5x30	BT-0530	3	115
3x40	BT-0340	3	90
4x40	BT-0440	3	115
5x40	BT-0540	3	150
6x40	BT-0640	3	200
5x50	BT-0550	4	200
6x50	BT-0650	4	250
8x50	BT-0850	4	2x150
6x60	BT-0660	4	2x150
8x60	BT-0860	4	2x200
10x60	BT-1060	4	500

BS



A	MOLD	P	W/M
2x20mm <sup>2</sup>	BS-0220	3	65
3x20	BS-0320	3	90
2x25	BS-0225	3	90
3x25	BS-0325	3	115
4x25	BS-0425	3	115
3x30	BS-0330	3	115
4x30	BS-0430	3	150
5x30	BS-0530	3	200
3x40	BS-0340	3	150
4x40	BS-0440	3	200
5x40	BS-0540	3	200
5x50	BS-0550	3	250
6x50	BS-0650	3	250
8x60	BS-0860	4	2x150
10x60	BS-1060	4	2x200



A	MOLD	P	W/M
2x20 <sub>mm</sub> <sup>2</sup>	BX-0220	3	45
3x20	BX-0320	3	65
4x20	BX-0420	3	65
5x20	BX-0520	3	65
2x25	BX-0225	3	65
3x25	BX-0325	3	90
4x25	BX-0425	3	150
5x25	BX-0525	3	150
2x30	BX-0230	3	90
3x30	BX-0330	3	115
4x30	BX-0430	3	200
5x30	BX-0530	3	200
3x40	BX-0340	4	250
4x40	BX-0440	4	150x2
5x40	BX-0540	4	200x2
6x40	BX-0640	4	150x3
5x50	BX-0550	4	200x3
6x50	BX-0650	4	200x3
8x50	BX-0850	4	250x3