







CATHODE PROTECTION CONNECTIONS







A	MOLD	P	W/M
4mm ²	CSHEA-4-D	1	CP-15
6	CSHEA-6-D	1	CP-15
10	CSHEA-10-D	1	CP-25
16	CSHEA-16-D	1	CP-32
25	CSHEA-25-D	1	CP-25
30	CSHEA-30-D	1	CP-32
35	CSHEA-35-D	1	CP-35
50	CSHEA-50-D	1	CP-45
70	CSHEA-70-D	1	CP-65

A	MOLD	P	W/M
4mm ²	CSHTA-4-D	1	CP-25
6	CSHTA-6-D	1	CP-25
10	CSHTA-10-D	1	CP-32
16	CSHTA-16-D	1	CP-45
25	CSHTA-25-D	1	CP-45
30	CSHTA-30-D	1	CP-45
35	CSHTA-35-D	1	CP-45
50	CSHTA-50-D	1	CP-45
70	CSHTA-70-D	1	CP-65





A	MOLD	P	W/M
10mm ²	SVES-10-D	1	CP-32
16	SVES-16-D	1	CP-32
25	SVES-25-D	1	CP-45
30	SVES-30-D	1	CP-45
35	SVES-35-D	1	CP-45
50	SVES-50-D	1	CP-65
70	SVES-70-D	1	CP-65



A	B	MOLD	P	W/M
6mm ²	6mm ²	WL-6/6	2	CP-25
10	4	WL-10/4	2	CP-25
10	6	WL-10/6	2	CP-25
10	10	WL-10/10	2	CP-25
16	6	WL-16/6	2	CP-32
16	10	WL-16/10	2	CP-32
16	16	WL-16/16	2	CP-32
25	10	WL-25/10	2	CP-32
25	16	WL-25/16	2	CP-32
25	10	WL-25/10	2	CP-45
30	16	WL-30/16	2	CP-45
30	25	WL-30/25	2	CP-45
30	30	WL-30/30	2	CP-65

A	B	MOLD	P	W/M
2.5mm ²	2.5mm ²	CWE-2.5/2.5	2	CP-15
4	4	CWE-4/4	2	CP-15
6	6	CWE-6/6	2	CP-15
10	10	CWE-10/10	2	CP-25
16	16	CWE-16/16	2	CP-25
25	25	CWE-25/25	2	CP-25
30	30	CWE-30/30	2	CP-32
35	35	CWE-35/35	2	CP-32



ORDER NO.

CJP _ A _ B

B DISTANT (mm)
A DISTANT (mm)

EXAMPLE:

FIVE CONNECTIONS:

A=75mm,B=125mm
MODL TYPE=CJP75A125B

IF TWO CONNECTIONS:

A=350mm,B=0mm
MODL TYPE=CJP350A0B

MOLD	P	W/M
CJP <u>A</u> BB	2	CP-15