


busbar to grounding rod connections


GVE




GBN



GBT







A	MOLD	P	W/M
1/2 inch	GVE-12	3	150
5/8 inch	GVE-15	4	200
3/4 inch	GVE-18	4	250

A	B	MOLD	P	W/M
1/2 inch	2x20 mm ²	GBN-12/0220	3	65
	2x25	GBN-12/0225	3	65
	2x30	GBN-12/0230	3	90
	3x20	GBN-12/0320	3	90
	3x25	GBN-12/0325	3	90
	3x30	GBN-12/0330	3	90
	3x40	GBN-12/0340	3	90
	3x50	GBN-12/0350	3	115
	4x20	GBN-12/0420	3	90
	4x25	GBN-12/0425	3	90
5/8 inch	2x30	GBN-15/0230	3	115
	3x20	GBN-15/0320	3	90
	3x25	GBN-15/0325	3	90
	3x30	GBN-15/0330	3	115
	3x40	GBN-15/0340	3	115
	3x50	GBN-15/0350	3	150
	4x20	GBN-15/0420	3	90
	4x25	GBN-15/0425	3	115
	5x25	GBN-15/0525	3	115
	5x30	GBN-15/0530	3	150
	5x40	GBN-15/0540	3	150
	5x50	GBN-15/0550	3	200
	6x25	GBN-15/0625	3	150
	6x30	GBN-15/0630	3	150
	6x40	GBN-15/0640	3	200
6x50	GBN-15/0650	3	200	


GBN



A	B	MOLD	P	W/M
3/4 inch	2x30	GBN-18/0230	3	150
	3x20	GBN-18/0320	3	115
	3x25	GBN-18/0325	3	150
	3x30	GBN-18/0330	3	150
	3x40	GBN-18/0340	3	200
	3x50	GBN-18/0350	4	2x150
	4x20	GBN-18/0420	3	150
	4x25	GBN-18/0425	3	150
3/4 inch	5x25mm ²	GBN-18/0525	3	150
	5x30	GBN-18/0530	3	200
	5x40	GBN-18/0540	3	200
	5x50	GBN-18/0550	4	2x150
	6x25	GBN-18/0625	3	200
	6x30	GBN-18/0630	3	250
	6x40	GBN-18/0640	4	2x200
	6x50	GBN-18/0650	4	2x200



A	B	MOLD	P	W/M
1/2 inch	2x20 mm ²	GBT-12/0220	3	65
	2x25	GBT-12/0225	3	65
	2x30	GBT-12/0230	3	90
	3x20	GBT-12/0320	3	90
	3x25	GBT-12/0325	3	90
	3x30	GBT-12/0330	3	90
	3x40	GBT-12/0340	3	90
	3x50	GBT-12/0350	3	115
	4x20	GBT-12/0420	3	90
	4x25	GBT-12/0425	3	90
5/8 inch	2x30	GBT-15/0230	3	90
	3x20	GBT-15/0320	3	90
	3x25	GBT-15/0325	3	90
	3x30	GBT-15/0330	3	115
	3x40	GBT-15/0340	3	115
	3x50	GBT-15/0350	3	200
	4x20	GBT-15/0420	3	90
	4x25	GBT-15/0425	3	115
	5x25	GBT-15/0525	3	115
	5x30	GBT-15/0530	3	150
	5x40	GBT-15/0540	3	150
	5x50	GBT-15/0550	3	200
	6x25	GBT-15/0625	3	150
	6x30	GBT-15/0630	3	150
	6x40	GBT-15/0640	3	200
6x50	GBT-15/0650	3	250	
3/4 inch	2x30	GBT-18/0230	3	150
	3x20	GBT-18/0320	3	150
	3x25	GBT-18/0325	3	150
	3x30	GBT-18/0330	3	150
	3x40	GBT-18/0340	3	200
	3x50	GBT-18/0350	4	2x150
	4x20	GBT-18/0420	3	150
	4x25	GBT-18/0425	3	200



A	B	MOLD	P	W/M
3/4 inch	5x25mm ²	GBT-18/0525	3	150
	5x30	GBT-18/0530	3	200
	5x40	GBT-18/0540	3	200
	5x50	GBT-18/0550	4	2x150
	6x25	GBT-18/0625	3	200
	6x30	GBT-18/0630	3	250
	6x40	GBT-18/0640	3	250
	6x50	GBT-18/0650	4	2x150